

VEHICLE INSPECTION REPORT

PF70EAW

Fiat Ducato 2.3 Multijet 140

Inspection

Serious Damage? No

Vehicle

VAT	Plus VAT
V5	To Follow
Cap Id	44906
Cap Code	FIDU233MM4BDTM2 5 L

Details

Location	Doncaster	Colour	MULTI-COLOURED	CAP Average	£3,700.00
Reg. date	27/01/2021	VIN	ZFA25000002P45081	CAP Below	£3,050.00
Year	2021	Body Style	Dropside MWB	Gearbox	MANUAL
Mileage	120,810 Miles Warranted	Service history	None	Gears	6
Fuel Type	DIESEL	MOT Due	07/02/2027		
GVW	3500kg	CAP Clean	£4,150.00		

WARNING LIGHT ON DASH AD-BLUE, E/MIRRORS

Tyres

NSF

NSR

OSF


OSR

Spare

Features


- Bluetooth connection
- Front electric windows
- Park assist camera
- Drivers airbag
- Digital radio
- Central locking
- Air conditioning
- Cloth seat trim

Photos





Condition Check



Damage Photos



1: Bumper Front Moulding
Scuffed (Unpainted)
Over 100mm



2: Bonnet
Chipped
Multiple Chips



3: Bumper Front Moulding
Scuffed (Unpainted)
UpTo 100mm



4: Wing nsf
Scratched
Over 25mm Not Thru Paint



5: Door nsf
Scratched
Over 25mm Thru Paint



6: Door nsf
Scratched
Over 25mm Thru Paint



7: B Post ns
Chipped
Multiple Chips



8: Door osf
Scratched
Over 25mm Thru Paint



9: Sill os
Dented
With Paint Damage



10: Carpets Front
Holed
Over 3mm



11: Seat Base Cover osf
Burn
Over 3mm



12: Dash Warning Lights
Displayed
No Action

Interior

Carpet Condition	Poor	Upholstery Condition	OK
Seat Condition	Poor	Odour	No
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	Fault	DPF light illuminated	OK
ABS light illuminated	OK		