

VEHICLE INSPECTION REPORT

BX09FYL

Daf LF 45.180

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 24/05/2009

VIN XLRAE45FF0L352695

Axle Combi 4x2

Year 2009

Body Style Mobile Workshop

Rear Suspension Steel

Mileage 322,987 Km Warranted

Service history Yes

Rear Doors Roller

Fuel Type DIESEL

Service documents Printout

Tail Lift Column

GVW 10000kg

Cab Type DAY CAB

Colour WHITE

Gearbox MANUAL

TAIL LIFT INOP SIDE DOOR, SINK, HOB

Tyres

NSF NSI1 NSI2 NSI3 NSI4

OSF OSI1 OSI2 OSI3 OSI4


Spare NSO1 NSO2 NSO3 NSO4



OSO1 OSO2 OSO3 OSO4

Features

- Cruise control
- Digital radio
- Front electric windows
- Central locking
- Cloth seat trim


Photos







Condition Check



Damage Photos



1: Panel Front
Scratched
Over 25mm Thru Paint

2: Bumper Front Moulding
Broken
Replace



3: Bumper Front Grill
Missing
Replace

4: Bonnet
Cracked
Replace



5: Panel Front
Scratched
Over 25mm Thru Paint

6: Door Mirror Assy nsf
Scuffed (Unpainted)
Over 100mm



7: B Post ns
Rusted
Over 5mm

8: Qtr Panel Moulding ns
Scratched (Painted)
Over 25mm Thru Paint



9: Qtr Panel Moulding ns
Scratched (Painted)
Over 25mm Thru Paint

10: Qtr Panel Moulding os
Scratched (Painted)
Over 25mm Thru Paint



11: Door osf
Scratched
Over 25mm Thru Paint

12: Carpets Front
Torn
Over 10mm



13: Door Pad osf
Soiled
Heavy

14: Seat Base Cover osf
Holed
Over 3mm



15: Seat Base Cover nsf
Soiled
Heavy

Interior

Carpet Condition	Poor	Upholstery Condition	Poor
Seat Condition	Poor	Odour	-
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		